










ASSEMBLY INSTRUCTION

NC * FXX & NC * MXX | XLR Cable Connector


- (A) Slide the boot onto the cable.
- (B) Prepare cable as shown.
- (C) Insert wires into the terminals and solder them.
- (D) Put chuck onto the cable.
Attention: Pay attention to the guiding key.
- (E) Slide insert and chuck together into the housing.
- (F) Finish the installation by turning the bushing onto the connector.
- 
- 
- 
- 
- 
- 
- ORDER OF ASSEMBLY**

NC *FXX



bushing chuck insert housing

NC *MXX



www.siluj.com



NEUTRIK